Wireless crane scale Technical Specification

Model: OCS-01



Description:

Auto battery capacity display

Overcharge and over discharge protection

IP65 waterproof and dust proof

High precision load cell, slight waggle will not affect weighing

Auto off, save power and battery's life span

Alarm: Overload, battery capacity less than 50%

Environmental Conditions: Temperature 0°C - +40°C, Humidity R.H<95%

Detailed parameters:

| Max. Capacity (kg) | Min. Capacity (kg) | Division (kg) |
|--------------------|--------------------|---------------|
| 1000 | 4 | 0.2 |
| 3000 | 10 | 0.5 |
| 5000 | 20 | 1 |
| 10000 | 40 | 2 |

| Accuracy class | III |
|--------------------|-----------------------|
| Tare weight | 100% of capacity |
| Stabilization Time | Within 10 second |
| Display | 5 digits,30mm LED/LCD |
| Factory proof load | 125% of capacity |
| Power | Rechargeable 6V/4AH |
| Remote Range | ≤20m |
| Temperature | 0°C – 40°C |